



**Firmware Release Note**

# **Prestige 645R-A1**

**Standard version**

**Release 3.40(GJ.2)C0**

**Date:** May 23, 2003  
**Author:** Ryan Jiang

# **Prestige P645R-A1 3.40(GJ.2)C0**

## **Release Note**

---

**Date:** May 23, 2003

### **Supported Platforms:**

---

Samsung 9847+9850+8951

### **Versions:**

---

ZyNOS Version: V3.40(GJ.2) | 5/23/2003 15:49:07

Bootbase Version: V1.07 | 5/21/2003 22:07:38

### **Notes:**

---

1. The P645R-A1 (ADSL Router) is a small-office and home device that will allow a small LAN to access the Internet. By integrating ADSL, and NAT capability, P645R-A1 provides not only the ease of installation and Internet access, but also the most completed security solution to protect your intranet and efficient network management for data traffic.  
The P645R-A1 provides four single auto-sensing, auto-detection 10/100BASE-T Ethernet ports for connection to the user's local network, and a single RJ-11 port for connection to ADSL line.

Main features:

- ADSL

- Support Multi-Mode standard (ANSI T1.413, Issue 2 ; G.dmt(G.992.1); G.lite(G.992.2)).
- Auto-negotiating rate adaptation
- ADSL physical connection ATM AAL5 (ATM Adaptation Layer type 5)
- Support multi-protocol over AAL5 (RFC1483)
- Support PPP over ATM AAL5 (RFC2364)
- PPP over Ethernet support for DSL connection (RFC 2516)
- Support VC-based and LLC-based multiplexing
- F4/F5 OAM

- Hardware

- One 10/100M Ethernet UTP ports for LAN connection

- Router

- NAT (includes multi-to-multi NAT) / SUA
- Packet Filter
- VPN (IPSec, PPTP, & L2TP) pass through support
- Port forwarding
- Embedded Web Configuration
- SNMP v1 & v2c with MIB II

•

**2. Modem code version: SAMSUNG, DSP Version 109.030225**

**3. Modem Setting :**

ADSL Standard	Multi
MinSNRMargin	6 db
TCM mode	ON
FEC R=2 mode	OFF
Tx Power attn	Normal db

## **Known Issues:**

---

## **Features:**

---

### **Modification in 3.40(GJ.2)b12 (May 23, 2003)**

1. [FEATURE ENHANCE] Add the CI command for the request of TE to decrease the test period.
2. [BUG FIXED]  
Symptom: The service provider default set to [WWW.DDNS.ORG](http://WWW.DDNS.ORG) not [WWW.DynDNS.ORG](http://WWW.DynDNS.ORG). The default setting should be [WWW.DynDNS.ORG](http://WWW.DynDNS.ORG).  
Condition: In the SMT and Web Configurator..  
Solution: Fix this bug by update the DDNS default setting.

### **Modification in 3.40(GJ.2)b11 (May 22, 2003)**

3. Update S5N8950 ADSL Debug Information to version 4.01.
4. Performance enhanced (about 20% in throughput test) by decrease SDRAM delay timer.  
Please also upgrade Bootbase to GJ1.07 when upgrade Ras to 3.40(GJ.2)b11.

### **Modification in 3.40(GJ.2)b10 (May 12, 2003)**

1. Change the default setting to ENET ENCAP from PPPoE.
2. Change ARM MAC Rx/Tx buffer descriptor number to 64 from 60.
3. Change ARM MAC Rx/Tx buffer descriptor start address to 8-bit alignment.
4. [BUG FIXED] Merge the bug fixed from trunk 3.40.
5. [BUG FIXED]  
Symptom: Press 13/14 in main menu, the system will accept under SMT & Telnet.  
Condition:  
Solution: Modify SMT Menu to fix this problem.

### **Modification in 3.40(GJ.2)b9 (May 08, 2003)**

1. Change the default setting to PPPoE from ENET ENCAP.

### **Modification in 3.40(GJ.2)b8 (February 28, 2003)**

## **ZyXEL Confidential**

### 1. [BUG FIXED]

Symptom: It's hard to link up with Siemens TI DSLAM in TianJin.

Condition: S5N8950 got some noise in the handshake state.

Solution: Update DSP code to 109.030225 to fix this problem.

### **Modification in 3.40(GJ.2)b4 (January 15, 2003)**

#### 1. [BUG FIXED]

Symptom: System can't receive the correct the VC through SAR

Condition: Happens only when configuring multiple PVC in bridge mode.

Solution: Fix SAR drive to keep upstream packet transmit smooth and alive.

#### 2. [BUG FIXED]

Symptom: Upstream rate will not change if the link rate changed to higher from lower.

Condition: Happens only when link rate changed from lower to higher.

Solution: Fix SAR drive to clear Connections after link down.

#### 3. [BUG FIXED]

Symptom: Upstream will stop if the AX4000 bi-direction stress test.

Condition: Happens only when configuring multiple PVC in bridge mode.

Solution: Add work-around function to SAR drive to reset Tx buffer if the SAR buffer is overflow.

#### 4. [BUG FIXED]

Symptom: S5N8950 TC Upstream will stop if the AX4000 bi-direction stress test, but the S5N8947 SAR still works.

Condition: Happens only when configuring multiple PVC in bridge mode.

Solution: Add work-around function to SAR drive to reset S5N8950 TC register if the SAR buffer is overflow.

### **Modification in 3.40(GJ.1)b3**

1. Change DSP code to version 109.151220.

### **Modification in 3.40(GJ.1)b2 (Nov 28, 2002)**

1. Change DSP code to version 109.021203.